# Weatherization Assistance

### Work Order Bid (ID)

#### **WORK ORDER INFORMATION**

Work Order Name: WO/15015SE2174/1Work Order Type: WeatherizationAudit Name: 15015SE2174Audit

**CLIENT INFORMATION** 

Client ID: 15015SE2174

#### **AGENCY INFORMATION**

Client ID: 15015SE2174

Agency:South East TN. Human Resource AgencyAgency Phone:(423) 949-2191Address:(PO Box 909) 1012 Resource RoadFax:(423) 949-4023

Dunlap, TN 37327 Email Address:

Agency Contact: Bloodworth, Darrell Work Phone:

Cell Phone: (423) 505-4585

**Email Address:** 

Company Name & License Number:	
Contractor's Signature:	

#### **COMMENT**

Certified Firm/Renovator Required 1950 site built with 1970 addition, approx 1332 sqft total, vinyl siding, 200 amp GE Breaker box in laundry

#### **Measures**

Client ID: 15015SE2174

Measur	e 1 Infilt	ration Redctn			Componen	ts			Inspected
Commen	nt Blower o	door 5535 Target 4000							
	Attic is to well as s Noted le	get due to wood ceilings to be considered non con seal any holes from attic. akage areas: attic, laund to (seal before insulating	nditioned s dry room, l	pace, v	w/s and swee	ep attic d ehind TV			
					Estimated			Actual	
# Material	/ Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Labor		Infiltration Reduction	CFM	1535					
1 Miscella	aneous Su	Infiltration Reduction	CFM	1535					
Other Deta	ail						7		
							] []		
				Moasur	e Sub Total:		] [] ]	Sub Total:	
Field No				Measur	e Sub Total.				
		Ceiling Cavity ttic under the attic floor			Componen		Attic2		Inspected
Commer	nt center a	ttic under the attic floor	Helio		Estimated	1		Actual	
Commer	nt center a	ttic under the attic floor  Description / Comment	<b>Units</b>	Qty	•		Attic2		Inspected Total
Commer	nt center a	ttic under the attic floor	<i>Units</i> SqFt		Estimated	1		Actual	
	nt center a	ttic under the attic floor  Description / Comment  Attic Insulation -		Qty	Estimated	1		Actual	
Commer # Material 1 Insulation	of center a	ttic under the attic floor  Description / Comment  Attic Insulation - Cellulose, Blown - 6 in.  Attic Insulation -	SqFt	<b>Qty</b> 336	Estimated	1		Actual	
Comment  # Material  1 Insulation  2 Labor	of center a	ttic under the attic floor  Description / Comment  Attic Insulation - Cellulose, Blown - 6 in.  Attic Insulation -	SqFt	<b>Qty</b> 336	Estimated	1		Actual	
Comment  # Material  1 Insulation  2 Labor	of center a	ttic under the attic floor  Description / Comment  Attic Insulation - Cellulose, Blown - 6 in.  Attic Insulation -	SqFt SqFt	<b>Qty</b> 336 336	Estimated Unit Cost	1	Qty	Actual Unit Cost	
# Material 1 Insulation 2 Labor Other Detail	of center a	ttic under the attic floor  Description / Comment  Attic Insulation - Cellulose, Blown - 6 in.  Attic Insulation -	SqFt SqFt	<b>Qty</b> 336 336	Estimated	1	Qty	Actual	
Comment  # Material  1 Insulation  2 Labor	of center a	ttic under the attic floor  Description / Comment  Attic Insulation - Cellulose, Blown - 6 in.  Attic Insulation -	SqFt SqFt	<b>Qty</b> 336 336	Estimated Unit Cost	1	Qty	Actual Unit Cost	
# Material 1 Insulation 2 Labor Other Detail	of center a	ttic under the attic floor  Description / Comment  Attic Insulation - Cellulose, Blown - 6 in.  Attic Insulation -	SqFt SqFt	<b>Qty</b> 336 336	Estimated Unit Cost	1	Qty	Actual Unit Cost	

-	Measure 3 DWH	Tank Insulation			Componen	ts			Inspected
C	<b>omment</b> 50 gal el	ectric							
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	<b>Unit Cost</b>	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
0	ther Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
		Pipe Insulation			Componen	ts			Inspected
	Measure 4 DWH omment 50 gal ele	•			Componen Estimated			Actual	Inspected
C		•	Units	Qty	-		Qty		Inspected
C	<b>omment</b> 50 gal el	ectric	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
<b>C</b> **	omment 50 gal el	ectric  Description / Comment		_	Estimated	1	Qty	Actual	
# 1 2	omment 50 gal element	ectric  Description / Comment  DHW Pipe Insulation	Each	1	Estimated	1	Qty	Actual	
# 1 2	omment 50 gal element	ectric  Description / Comment  DHW Pipe Insulation	Each	1	Estimated	1	Qty	Actual	
# 1 2	omment 50 gal element	ectric  Description / Comment  DHW Pipe Insulation	Each	1	Estimated	1	Qty	Actual	
# 1 2	omment 50 gal element	ectric  Description / Comment  DHW Pipe Insulation	Each  Each	1 1	Estimated	1		Actual	
# 1 2 O	omment 50 gal element	ectric  Description / Comment  DHW Pipe Insulation	Each  Each	1 1	Estimated Unit Cost	1		Actual Unit Cost	
# 1 2 O	omment 50 gal element	ectric  Description / Comment  DHW Pipe Insulation	Each  Each	1 1	Estimated Unit Cost	1		Actual Unit Cost	

Measure 5 Floo	or Ins. R-19			Componen	ts Crawl	space1		Inspected
Comment 2x8 240	С							
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	784					
2 Labor	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	784					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:						_		
Measure 6 Floo Comment 2x8 160				Componen	ts Crawl	space2	,	Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	324					
2 Labor	Floor Insulation -	SqFt	324					
	Fiberglass Faced Batt - R-19							
3 Miscellaneous Su								
Other Detail	Added Misc Cost	Each	1					
Curio: Dotain	Added Misc Cost	Each	1					
	Added Misc Cost	Each	1					
	Added Misc Cost	Each	1					
	Added Misc Cost			re Sub Total:			Sub Total:	
Field Notes:	Added Misc Cost			re Sub Total:			Sub Total:	
	Added Misc Cost			re Sub Total:			Sub Total:	
	Added Misc Cost			re Sub Total:			Sub Total:	

1	Measure 7 Wal	l Insulation			Componen	sts E1,E2 S2,W	,E3,N1	,N2,S1,	Inspected
C	<b>Comment</b> Repair	hole behind tv in front bed	droom pric	or to fil	•			Antoni	
#	Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
1	Insulation	Wall Insulation - Cellulose, Blown - 2x4 Filled	SqFt	1061					
2	Labor	Wall Insulation - Cellulose, Blown - 2x4 Filled	SqFt	1061					
(	Other Detail								
L					] [][		] [		
				Measu	re Sub Total:			Sub Total:	
	Field Notes:								

	<i>Measure</i> 8 Insta	II Heatpump			Componen	ts Heat1	,AC1		Inspected
C	Manual I repair ho properly	or to determine proper u D. Contractor to remove ble. Contractor to remove dispose of. There is NO ermostat.	AC (prope LP heate	erly dis er from	pose of) fror front living r	n kitchen oom and	and		
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	<b>Unit Cost</b>	Total
1	Heating Equipmen	Heatpump - 25 kBtu/h Existing, Consult Manual J Data	Each	1					
2	Labor	Heatpump - 25 kBtu/h Existing, Consult Manual J Data	Each	1					
(	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

#### Measure 9 Attic Ins. R-30

## **Components** Addition Attic, Main Attic1, Main Attic3

Ins	pe	cte	d
1113	$\sim$	Cic	u

Comment Front attic (Main Attic1) (attic behind kneewall in orig house)
Back attic (Main Attic3) (attic behind kneewall in orig house)
Addition Attic, access thru window in main attic, vent kitchen exhaust to

	outside								
					Estimated	<i>1</i>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1	Labor	Attic Insulation - Cellulose, Blown - R-30	SqFt	324					
1	Insulation	Attic Insulation - Cellulose, Blown - R-30	SqFt	324					
2	Labor	Added Misc Cost (Vent kitchen exhaust to outside)	Each	1					
2	Miscellaneous Su	Added Misc Cost (Vent kitchen exhaust to outside)	Each	1					
3	Insulation	Attic Insulation - Cellulose, Blown - R-30	SqFt	196					
3	Labor	Attic Insulation - Cellulose, Blown - R-30	SqFt	196					
4	Insulation	Attic Insulation - Cellulose, Blown - R-30	SqFt	196					
4	Labor	Attic Insulation - Cellulose, Blown - R-30	SqFt	196					
C	Other Detail								
	,			Measur	e Sub Total:			Sub Total:	
	Field Notes:								

	Measure 10 CO N	Monitor is Needed			Componen	ts		1	Inspected
C	<b>comment</b> Back far	nily room where LP heat	er to rema	iin					
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	<b>Unit Cost</b>	Total
1	Health and Safety	CO monitor	Each	1					
2	Labor	Labor	Each	1					
C	Other Detail								
				Measur	e Sub Total:		] ;	Sub Total:	
	Field Notes:								
	Measure 11 Fix I	mproper Venting (Cloth	nes Dryer	)	Componen				Inspected
C		mproper Venting (Cloth	nes Dryer		Componen  Estimated  Unit Cost		Qty	Actual Unit Cost	Inspected
<i>C</i>	Comment	Description / Comment		Qty 1	Estimated	<u> </u>	Qty	Actual	
# 1	Comment  Material / Labor	Description / Comment	Units	Qty	Estimated	<u> </u>	Qty	Actual	
# 1	Comment  Material / Labor  Health and Safety  Labor	Description / Comment approx 6 LNFT	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
# 1	Comment  Material / Labor  Health and Safety	Description / Comment approx 6 LNFT	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
# 1	Comment  Material / Labor  Health and Safety  Labor	Description / Comment approx 6 LNFT	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
# 1	Comment  Material / Labor  Health and Safety  Labor	Description / Comment approx 6 LNFT	Units Each Each	<b>Qty</b> 1 1	Estimated	<u> </u>		Actual	
# 1	Comment  Material / Labor  Health and Safety  Labor	Description / Comment approx 6 LNFT	Units Each Each	<b>Qty</b> 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# 1	Material / Labor Health and Safety Labor Other Detail	Description / Comment approx 6 LNFT	Units Each Each	<b>Qty</b> 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

ı	Measure 12 Pres	sureRelief Piping Need	ded		Componen	its			Inspected
C	omment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Pressure relief piping	Each	1					
2	Labor	Labor	Each	1					
0	Other Detail								
				Measur	e Sub Total:		] ,	Sub Total:	
	Measure 13 RRP	Compliance ulation and Heatpump in	stallation		Component Estimated			Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Unspecified	RRP Compliance	Each	1		Total	Qiy	Omit Cost	Total
0	Other Detail								
Ĭ	varier Bottan								
				Measur	e Sub Total:		] ,	Sub Total:	
	Field Notes:								

Measure 14 Vapo and	or Barrier Needed (Crav 2)	vlspace1		Componen	ts			Inspected
	ace1 is orig house, Craw room/bathroom (this crav					pace3 i	S	
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Basement / crawlspace vapor barrier	SqFt	1108					
2 Labor	Labor	SqFt	1108					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work Or	rder Gra	nd Total:		Gran	d Total:	

Client ID: 15015SE2174